

Administration

EUGENE EABORN
PRESIDENT
EABORN TRUCK SERVICE INC
1300 CRAFTON BLVD
PITTSBURGH, PA 15205-3626

1200 New Jersey Ave., S.E. Washington, DC 20590 October 25, 2010

In reply refer to: Your USDOT No.: 85172 Review No.: 832474/CR

Dear EUGENE EABORN:

The motor carrier safety rating for your company is:

SATISFACTORY

This SATISFACTORY rating is the result of a review and evaluation of your safety fitness completed on October 19, 2010. A SATISFACTORY rating indicates that your company has adequate safety management controls in place to meet the safety fitness standard prescribed in 49 C.F.R. 385.5.

Please assure yourself that any specific deficiencies identified in the review report have been corrected. We appreciate your efforts toward promoting motor carrier safety throughout your company. If you have questions or require further information, please contact:

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION
228 WALNUT STREET, ROOM 560
HARRISBURG, PA 17101
Telephone No.: 717-221-4443

John Van Steenburg

Director, Office of Enforcement and

We Quelon

Compliance